

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15959.8

Dispenser #2 32667.4

Dispenser #3 37322.0


Dispenser #4 47796.6

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

Jan 3

Time

805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15952.8

Dispenser #2 32667.9

Dispenser #3 37322.3

Dispenser #4 42796.4

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

Jan 4

Time

830

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15954.8

Dispenser #2 32667.4

Dispenser #3 37722.0

Dispenser #4 47796.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date Jan 5 Time 805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15957.8

Dispenser #2 326674

Dispenser #3 37322.0

Dispenser #4 47796.2

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date Jan 7 Time 800

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15954.8

Dispenser #2 32667.5

Dispenser #3 37322.0

Dispenser #4 47796.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Jan 7

Time 1200

Morning Inspection Sheet

Dock inspection

_____ All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

_____ All boats secure and tied correctly. Waterlines ok?

_____ Any new boats arrived ?

Fuel dock

_____ All fire cabinets secure.

_____ Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 _____

Dispenser #2 _____

Dispenser #3 _____

Dispenser #4 _____

_____ No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

_____ Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign _____ Date _____ Time _____

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15954.8

Dispenser #2 72667.6

Dispenser #3 37322.4


Dispenser #4 47790.6

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

Jan 10

Time

10:00

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15954.8

Dispenser #2 32667.6

Dispenser #3 37322.0

Dispenser #4 47796.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Jan 11

Time 800

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15952.8

Dispenser #2 32667.6

Dispenser #3 37322.0

Dispenser #4 47796.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date Jan 12 Time 804

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15954.8

Dispenser #2 32667.0

Dispenser #3 37732.0 ← WRONG

Dispenser #4 cannot read

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date Jan 13 Time 805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15959.8

Dispenser #2 32667.0

Dispenser #3 37322.0


Dispenser #4 47796.0

leak still ok
No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

Jan 16

Time

836

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

29' Regal Motorboat - black - no CF#
Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15954.8

Dispenser #2 32667.6

Dispenser #3 37732.0 37322

Dispenser #4 47796.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date

Jan 17

Time

805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Beneteyo - 40-45 - Sogran ^{no CF #}
Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15954.8

Dispenser #2 32667.6

Dispenser #3 37322.0


Dispenser #4 47796.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

Jan 18

Time

817

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

*Cheoy Lee needs attention
or to be moved*

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15954.8

Dispenser #2 32667.7

Dispenser #3 37327.6

Dispenser #4 47796.6

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign 

Date

Jan 19

Time

910

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

*Penetecan needed attention
Decklines*

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15954.8

Dispenser #2 32669.6

Dispenser #3 37322.6


Dispenser #4 47796.6

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

Jan 20

Time

8:15

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15954.8

Dispenser #2 727920

Dispenser #3 373220

Dispenser #4 477969

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date 1/23/19 Time 8:40

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15959.8

Dispenser #2 32792.0

Dispenser #3 37322.0

Dispenser #4 47796.9

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date

Jan 24

Time

809

Morning Inspection Sheet

Dock inspection

_____ All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

_____ All boats secure and tied correctly. Waterlines ok?

_____ Any new boats arrived ?

Fuel dock

_____ All fire cabinets secure.

_____ Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 _____

Dispenser #2 _____

Dispenser #3 _____

Dispenser #4 _____

_____ No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

_____ Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign _____ Date _____ Time _____

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15953.8

Dispenser #2 32792.7

Dispenser #3 37322.0

Dispenser #4 47796.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Jan 25

Time 815

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15954.8

Dispenser #2 327927

Dispenser #3 37322.0

Dispenser #4 477969

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Jun 26

Time 805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 159770

Dispenser #2 32792.9

Dispenser #3 377???

Dispenser #4 477969

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign 

Date

Jan 20

Time

805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Need to power wash!

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 159770

Dispenser #2 32793.0

Dispenser #3 37330.0 *needs to be cleaned*

Dispenser #4 47796.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign *[Signature]*

Date Jan 31

Time 807

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 159770

Dispenser #2 32793.4

Dispenser #3 373260


Dispenser #4 17872.4

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

Feb 1

Time

805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15977.0

Dispenser #2 32793.4

Dispenser #3 37336.0

Dispenser #4 47872.1

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date

Feb 2

Time

805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 159770

Dispenser #2 32793.3

Dispenser #3 37336.0

Dispenser #4 47872.1

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date Feb 3 Time 805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived? 31' Sundancer "Cutie"

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 159770

Dispenser #2 32797.5

Dispenser #3 37336.0

Dispenser #4 478990

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Feb 6

Time 830

Morning Inspection Sheet

Dock inspection

_____ All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

_____ All boats secure and tied correctly. Waterlines ok?

_____ Any new boats arrived ?

Fuel dock

_____ All fire cabinets secure.

_____ Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 _____

Dispenser #2 _____

Dispenser #3 _____

Dispenser #4 _____

_____ No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

_____ Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign _____ Date _____ Time _____

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 159770

Dispenser #2 327936

Dispenser #3 379363

Dispenser #4 47899.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Feb 7

Time 910

Chevy Lee (Hart) has taken out his windows and rain sets in quickly now

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 159770

Dispenser #2 327936

Dispenser #3 373360

Dispenser #4 97899.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign

Date

Feb 8

Time

802

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived? 27' Carver CF9364 JZ

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15977.0

Dispenser #2 32793.7

Dispenser #3 37336.2

Dispenser #4 47899.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date Feb 9 Time 807

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15977.0

Dispenser #2 72793.7

Dispenser #3 37336.0

Dispenser #4 47899.9

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Feb 10

Time 809

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived? CF 8560 GT "Maderira"

CF 2119 PG Sander
Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15977.0

Dispenser #2 32793.0

Dispenser #3 37336.0

Dispenser #4 47955.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Feb 13

Time 3:30

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Cherry Lee is opened up to be aired out. Close before rains come

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15977.0

Dispenser #2 32793.8

Dispenser #3 37336.0

Dispenser #4 47955.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date Feb 14 Time 8:00

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Chris Hart will be here with tags for his Chevy Lee before the rain. If not close all hatches.

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15977.0

Dispenser #2 32793.8

Dispenser #3 37339.0

Dispenser #4 47955.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Feb 15

Time 8:05

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15977.0

Dispenser #2 32797.0

Dispenser #3 37352.4


Dispenser #4 47955.4

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

Feb 16

Time

805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15977.0

Dispenser #2 32793.8

Dispenser #3 32352.0

Dispenser #4 47956.4

^{Diesel leak!} No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date Feb/17 Time 805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15972.0

Dispenser #2 32797.8

Dispenser #3 37382.0

Dispenser #4 47955.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign

Date

Time

[Signature]
Feb 21 845

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15977.0

Dispenser #2 32793.8

Dispenser #3 37732.0

Dispenser #4 47955.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Feb 22

Time 805

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15977.0

Dispenser #2 72793.8

Dispenser #3 47752.0

Dispenser #4 47955.4

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Feb 23

Time 810

Water is off, install new PVC today

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15977.0

Dispenser #2 32793.8

Dispenser #3 37352.0

Dispenser #4 47955.1

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date Feb 24 Time 8:07

Water main is fixed and dock is looking good! Happy Friday!

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 10002.6

Dispenser #2 32793.8

Dispenser #3 97351.2

Dispenser #4 46031.1

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date

Feb 27

Time

8:05

Water off because of a leak

Morning Inspection Sheet

Dock inspection

_____ All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

_____ All boats secure and tied correctly. Waterlines ok?

_____ Any new boats arrived ?

Fuel dock

_____ All fire cabinets secure.

_____ Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 _____

Dispenser #2 _____

Dispenser #3 _____

Dispenser #4 _____

_____ No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

_____ Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign _____ Date _____ Time _____

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16009.8

Dispenser #2 32793.8

Dispenser #3 37352.4

Dispenser #4 48031.0

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date Feb 28 Time 800

Water leak continues

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16009.8

Dispenser #2 32793.8

Dispenser #3 37777

Dispenser #4 48031.4

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date March 1 Time 800

~~N~~ Power wash hold shift

Water leak continues

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16009.8

Dispenser #2 32793.8

Dispenser #3 37341.0

Dispenser #4 48031.4

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date March 2 Time 800

Water leak continues
Power wash 90°

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16007.8

Dispenser #2 32797.0

Dispenser #3 37346.0

Dispenser #4 48081.4

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Merch 3

Time 800

Clean bird shot

Water leak continues

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16009.7

Dispenser #2 32793.8

Dispenser #3 37361.0

Dispenser #4 48031.4

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date March 6

Time 820

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 37364.0

Dispenser #4 48131.4

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date March 9

Time 8:05

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 37364.0


Dispenser #4 48131.4

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

March 10

Time

800

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived? Sheriff boat (North River)

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 37364.0

Dispenser #4 48268.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date March 13

Time 820

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived? Bene tow (Misty) 32-36' CF 9853 PR

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32703.8

Dispenser #3 37364.0

Dispenser #4 48268.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date _____ Time 600

Morning Inspection Sheet

Dock inspection

All floats and gangways **secure** and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats **secure** and tied correctly. Waterlines ok?

Any new boats arrived? Sundancer 330 no CF#

Fuel dock

All fire cabinets **secure**.

Fuel shack **secure** and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 37364.0


Dispenser #4 48309.4

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

March 15

Time

8:02

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived? Bene tau First 30

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 37364.3

Dispenser #4 48309.2

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date March 16

Time 8:05

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 37366.0

Dispenser #4 48809.8

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date March 17

Time 803

Prepare dock for possible weekend rain

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 37364.0

Dispenser #4 48408.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date March 20

Time 8:20

Ugly POS bayliner finally gone,
Durkin end of dock with lots of movement

Morning Inspection Sheet

Dock inspection

All floats and gangways **secure** and safe (no holes, **loose** decking etc.) No water leaks. **No** loose debris on docks. Hoses and power cords stowed properly.

All boats **secure** and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets **secure**.

Fuel shack **secure** and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16010.9

Dispenser #2 32194.0

Dispenser #3 37364.5

Dispenser #4 48408.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature]

Date Merch 21

Time 805

Misty need extra lines

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 3736.4

Dispenser #4 48408.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign

Date

Time

[Signature] March 24 835

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived? No

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

NEEDS RAGS

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 37364.5

Dispenser #4 49408.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

3-27-17

Time

8:15

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 37366.4

Dispenser #4 48408.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign

Ry

Date

3-28-17

Time

005

*More still leaking, cleaned areas
and replaced absorber pads*

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 37346.4

Dispenser #4 48408.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked. *METER LEAK OK*

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign 

Date

3-29-17

Time

810

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 _____

Dispenser #2 _____

Dispenser #3 _____

Dispenser #4 _____

METER TO BE INSTALLED TOMORROW
 No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign  Date 3-30-2017 Time 810

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16011.9

Dispenser #2 32793.8

Dispenser #3 37366.4

Dispenser #4 48408.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign JDC Date 3-31-17 Time _____

New Meter in DIESEL pump installed
SHORESIDE DIESEL

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived? SHUTTLE BOAT ARRIVED

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

NEEDS CLEANING

Dispenser #1 16001.9

Dispenser #2 32803.1

Dispenser #3 37392.3

Dispenser #4 48408.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date 4-3-17 Time 9

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 ~~16075.9~~ 16075.9

Dispenser #2 32803.1

Dispenser #3 37392.3

Dispenser #4 48108.7

Rust: Pump panel
OUTSIDE pump NEEDS
Replacement.

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign [Signature] Date 4-4-12 Time 055

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 _____

Dispenser #2 _____

Dispenser #3 _____

Dispenser #4 _____

*NEED TO REPLACE
PUMPS (rust: has to read)*

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign

[Signature]

Date

4-5-17

Time

8:30

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived? *Banner?*

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 _____

Dispenser #2 _____

Dispenser #3 _____

Dispenser #4 _____

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign



Date

4-6-17

Time

*Have Ryan get rid of oily rags
someone left on dock.*

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16092.8

Dispenser #2 32803.1


Dispenser #3 ~~33037~~ Can't read

Dispenser #4 48408.7

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign  Date 4-7-17 Time 7:55

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok? *TIGHTEN UNIONS*

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 _____

Dispenser #2 _____

Dispenser #3 _____

Dispenser #4 _____

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

REMOVED TAPE AT VALVES TO INSPECT DIESEL VALVE BODY ? SWEATING?

Immediately report any problems with above list to supervisor.

Sign *JDE* Date 4-10-17 Time _____

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 _____

Dispenser #2 _____


Dispenser #3 _____

Dispenser #4 _____

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign  Date 4-11-17 Time 8

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 15952.3

Dispenser #2 32756.7


Dispenser #3 Can't read

Dispenser #4 40885

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign  Date 4-12-17 Time 10:00

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 ~~15952.2~~ 15952.2

Dispenser #2 32852.1


Dispenser #3 _____

Dispenser #4 40001.5

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign  Date 4-13-17 Time 750

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 _____

Dispenser #2 _____


Dispenser #3 _____

Dispenser #4 _____

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign  Date 4-14-17 Time 740

GATE UNLOCKED LEFT OPEN ??

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16002.5

Dispenser #2 32852.1


Dispenser #3

Dispenser #4 48881.5

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign  Date 4-17-17 Time 8 AM

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 ~~16002.0~~ 16002.5

Dispenser #2 32878.0


Dispenser #3 _____

Dispenser #4 48881.5

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign  Date 4-18-17 Time 8

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived ?

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16107.7

Dispenser #2 32878.0


Dispenser #3 Credit read

Dispenser #4 49036.5

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Immediately report any problems with above list to supervisor.

Sign  Date 4-19-17 Time 9:20

Morning Inspection Sheet

Dock inspection

All floats and gangways secure and safe (no holes, loose decking etc.) No water leaks. No loose debris on docks. Hoses and power cords stowed properly.

All boats secure and tied correctly. Waterlines ok?

Any new boats arrived? No

Fuel dock

All fire cabinets secure.

Fuel shack secure and clean. Spill prevention items (rags, absorber pads, booms) in place.

Fuel pump readings

Dispenser #1 16102.7

Dispenser #2 32878.0

Dispenser #3 check tank

Dispenser #4 49036

No leaks around pumps (or fumes from unseen leaks) and pumps are locked.

Piping and valves inspected for leaks or abnormalities

Continuous inspections

Immediately report any problems with above list to supervisor.

Sign



Date

4-20-17

Time

745